PAGE 46/47 05/01/2012 17:03 8653543869 FURIN APPROVED Division of Health Care Facilities (X3) DATE SURVEY STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION COMPLETED AND PLAN OF CORRECTION IDENTIFICATION NUMBER: A. BUILDING 01 - MAIN BUILDING 01 B. WING 04/16/2012 TN0101 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 100 ELMHURST DR BRIARCLIFF HEALTH CARE CENTER OAK RIDGE, TN 37830 PROVIDER'S PLAN OF CORRECTION (X5) COMPLETE SUMMARY STATEMENT OF DEFICIENCIES (X4) 1D (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE (EACH DEFICIENCY MUST BE PRECEDED BY FULL. PREFIX PREFIX TAG REGULATORY OR LSC IDENTIFYING INFORMATION) TAG DEFICIENCY) N 831 N 831 1200-8-6-.08 (1) Building Standards N-831 5-19-12 (1) A nursing home shall construct, arrange, and Penetrations in the storage area at the maintain the condition of the physical plant and entrance of the freezer, in the shower the overall nursing home environment in such a room in the west wing, and in the manner that the safety and well-being of the mechanical room outside of physical residents are assured. therapy will be repaired. The Director of Maintenance will inspect all other areas in the facility, if any other areas with penetrations are identified, This Rule is not met as evidenced by: the Director of Maintenance will repair Based on observation the facility failed to as necessary. maintain the condition of the building. The Director of Maintenance will complete monthly building inspections to The findings include: ensure compliance is maintained. Observation on April 18, 2012 between 9:30 a.m. The Administrator or designee will and 11:30 a.m. revealed that the facility has randomly observe for penetrations for 3 penetrations in the following locations: months. Results will be discussed in the Storage area at the entrance of the freezer monthly Continuous Quality Improvement meeting comprised of the has a penetration around the receptacle and the DON, Risk Manager, Medical Director, wiring running through the wall above head. Social Services Director, Dietary 2. The shower room in the West Wing, in the Manager, Rehab Director, Staff first shower stall has a penetration in the Development Coordinator, Admissions recessed heater. Director, Activities Director, Restorative Mechanical room outside of the Physical Nurse, Wound Care Nurse, Director of Therapy area has a penetration in the ceiling Medical Records and Administrator for around the wiring. Quality Assurance. Based on observation the facility failed to maintain the condition of the building. The findings include:

Division of Health Care Facilities

TITLE

(X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Observation on April 18, 2012 at 11:25 a.m. revealed that one (1) of two (2) piece of the duct work the grill was rusted off and the other duct

work the grill had been removed.

STATE FORM

CORR

634W21

If continuation sheet 1 of 2

Division of Health Care Facilities

(X3) DATE SURVEY COMPLETED STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER; (X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING TN0101 04/16/2012

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

100 FLMHURST DR

BRIARCLIFF HEALTH CARE CENTER 100 ELM OAK RID		100 ELMHURST DR OAK RIDGE, TN 3783	IHURST DR DGE, TN 37830		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FUREGULATORY OR LSC IDENTIFYING INFORMATION OF THE PROPERTY OF THE PROP	JLL PREFIX ON) TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETI DATE	
N 831	Continued From page 1 These findings were verified by the Mainte Supervisor and acknowledged by the Administrator during the exit conference of 18, 2012.				
84				v	

Division of Health Care Facilities